



## **MONTEREY BAY**

Unified Air Pollution Control District  
serving Monterey, San Benito, and Santa Cruz counties

AIR POLLUTION CONTROL OFFICER  
Douglas Quetin

24580 Silver Cloud Court • Monterey, California 93940 • 831/647-9411 • FAX 831/647-8501

### **\*\*\*COMPLIANCE ADVISORY\*\*\***

## **Regarding Healy 900 EVR Nozzle**

February 8, 2008

To: Gasoline Dispensing Facility Owners/Operators, Contractors and  
Parts Houses

---

It has been determined by the State Air Resource Board (ARB) that most Healy 900 nozzles manufactured in 2007 are not as the nozzles were certified by the ARB for this system, and therefore Franklin Fueling Systems is in violation of State and District Regulations. California Health & Safety Code (H&SC) Section 41954(f) and District Rule 1002 prohibit the sale and installation of uncertified equipment, and the replacement of one part in the nozzle in 2007 made those nozzles uncertified. Franklin Fueling Systems has agreed to replace this part in all 2007 Model 900 nozzles in the state by April 15, 2008.

Due to this issue, any new Healy nozzles installed at any station (whether new or existing) in the District must be model year 2006 or 2008 nozzles, or a Healy rebuilt 2007 nozzle. Selling or installing an uncertified 2007 nozzle is a violation of H&SC 41954(f) and District Rule 1002. The model year is contained in the nozzle serial number, located on the bottom of the handgrip of the nozzle, as follows: XX YY Z, where YY indicates the model year (06, 07, 08).

Owners/operators should contact their distributor, to let them know of any 2007 model year nozzles at the facility, and arrange parts replacement.

Should you have any questions regarding this advisory please contact Teresa Sewell or Gene Mason at (831) 647-9411.